



# Inspections Bulletin

Subject:  
**(EXTERIOR)  
ADHERED CONCRETE  
MASONRY STONE VENEER**

Bulletin Number:  
**2010-02**

Effective Date:  
**1/1/2011**

The Town of Wake Forest Inspections Department is implementing some changes in its inspections of *ADHERED CONCRETE MASONRY STONE VENEERS* that are installed on the **EXTERIOR** of the structure.

Beginning JANUARY 1, 2011, The Town of Wake Forest Inspections Department will require the current installation instructions and the current ICC-ES report for the manufactured stone veneer that is being used. These requirements are to be on site at the required inspection. The required inspection is prior to the scratch coat being applied. If these documents are not on site as specified, the inspection will be considered as "**NOT READY**" and rejected. If the *ADHERED CONCRETE MASONRY STONE* being used does not have both of these documents, the stone installation will not be allowed. These documents must be followed completely.

Prepared By:  
**JDP**

Approved By:  
**JJC**